

Chapman A No. 1

Section 29, T23N, R6W
Sandoval County, New Mexico


SLOPE TESTS

Depth

Hole Deviation

231
1659
2865
4753

1/4°
3/4°
1-1/2°
1-1/2°



State of New Mexico)
County of San Juan) ss

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 5th day of May, 1982.

Rolanda Strange
Notary Public

My Commission Expires 10/28/85