

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
BLM

APR 15 PM 12:56  
SANDOVAL, N.M.

FORM APPROVED  
Budget Bureau No. 100a-1135  
Expires September 30, 1990

5. Lease Designation and Serial No.

NM - 15841

6. If Indian, Allotment or Tribal Name

----

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

CELSIUS ENERGY COMPANY

3. Address and Telephone No.

1125 17th Street, Suite 2240, Denver, Colorado 80202

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1520' FNL, 790' FEL  
Section 5, Township 22 North, Range 7 West

7. If Land or CA, Agreement Designation

FEDERAL 5

8. Well Name and No.

1-4

9. API Well No.

10. Field and Pool, or Exploration, Area

WIDE CAT Rusty  
Chacra

11. County or Parish, State  
SANDOVAL, N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or  
Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 4/12/91 the above captioned well was plugged and abandoned in accordance with the approved Sundry Notice dated 1/30/91. The well was plugged as follows:

- 1) A cast iron bridge plug was set at 1700' and pressure tested to 500 psi for 15 minutes - Held OK.
- 2) The hole was filled with 9.0 ppg mud.
- 3) The bridge plug was capped with 10 sacks of Class "G" cement. The plug was 129' in length and exists from 1700'-1571' KBM.
- 4) The second plug was a 20 sack plug that exists from 1447'-1195' (252' in length).
- 5) The third plug was a 20 sack plug from 1000'-691' (309').
- 6) The fourth plug was a 10 sack plug from 250'-surface.

The annulus 4-1/2"x7" was filled with cement (5 sacks) and a dry hole marker installed. The mud pit was back filled and deadmen anchors removed. Reclamation will take place at a later date.

NOTE: Ken Townsend was notified of the intention to P&A the well on 4/9/91 at 9:05 AM.

14. I hereby certify that the foregoing is true and correct.

Signed

*E. Marsh* FOR ARL

Title Sr. Petroleum Engineer

Date 4/12/91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

APPROVED

APR 15 1991

*Ken Townsend*

FOR AREA MANAGER  
CARMINGTON RESOURCE AREA