F. Loc	1850/s;	990/I	J E		. 7	30-04 167 GL	13-20652				7-16-8	2	PB		
Casing S Csg.Perf.		w	Sx.	Int	Elev	w	Sx. Pr Prod. Stim.		p	¹	rDSx. r	F	°8 @	Ţ	
.Р	BO/D MCF/D A	fter	Hrs.	SICP	PS	l After	Days GOR	G	rav.		Let Del			A N S	
			#			Well Log		TEST DAT	A		rsr Dei		5		
Kirtland			C-103			Plat	×	Schd.	PC	Q	PW	PD	П	10/2	
Fruitland			C-104			Electric Log				†		+	-	Ref.No	
Pictured Cliffs						C-122				 	 	 	 	 	
Cliff House			Ditr	_		Dfa				 	 -	 	<u> </u>		
Menefee			Datr			Dac		 			 -	 			
Point Lookout			/			·					<u> </u>				
Mancos												L			
Goilup											 				
Sanostee															
Greenhorn															
Dakota		$\neg \neg$!												
Morrison															
Entrada							1								
	—						160								
		1													
Chac.Dak	Ex te . S	A \$ 4	12	22N R	3W U	I ^{Oper} Chac	e Oil Comp	pany,	Inclse.	Jic.Tı	cib.Cor	nt 54	No.	12	

Jicarilla Tribal Cont 54 #12 I-4-22N-3W

CHACE OIL COMPANY

Caller Service 4104 Farmington, New Mexico 87499

CERTIFIED

Chace 0il Company, Inc. 313 Washington, SE Albuquerque, New Mexico 87108 27 JAN 1984

Gentlemen:

Reference is made to your Application for Permit to Brill (APD) well No. 54-12 Jicarilla Tribal Contract 54, NEASEA sec. 4, T. 22 N., R. W., Rio Arriba County, New Mexico, Jicarilla Contract 54. As discussed with Ross Easterling of your Company on January 17, 1984, the subject APD is hereby rescinded and returned due to drilling operations not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this Office if construction activities occurred on the referenced drill site. If this Office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,

Area Manager

Enclosure

cc: BIA, Dulce NMOCC/



OIL CON. DIV.

