

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-24445	
2. NAME OF OPERATOR Gary-Williams Oil Producer, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A	
3. ADDRESS OF OPERATOR 115 Inverness Drive East, Englewood, CO 80112-5116		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2107' FWL & 1789' FNL (SE NW) Section 32-T21N-R3W		8. FARM OR LEASE NAME Tayler 32	
14. PERMIT NO.		9. WELL NO. 6	
15. ELEVATIONS (Show whether on, at, or, etc.) 6985' GR		10. FIELD AND POOL, OR WILDCAT Rio Puerco Mancos	
		11. SEC., T., R., M., OR B.E. AND SURVEY OR AREA SE NW 32-T21N-R3W	
		12. COUNTY OR PARISH Sandoval	
		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) Request to temporarily SI well <input checked="" type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. IS A PROPOSED OR COMPLETED OPERATION? (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

the Tayler 32, #6 well for an indefinite time period. Current depressed oil prices make this marginal well uneconomical to produce.

The Tayler 32, #6 well was shut in on March 8, 1986. Production averaged 3.4 BOPD in February, 1986 and 2.7 BOPD for the first few days of March, 1986.

Approval for temporary shut in status for this well would prevent premature abandonment of significant recoverable hydrocarbon reserves.

RECEIVED

JUN 02 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

This Approval or Temporary
Abandonment Expires 6-12-87

JUN 12 1986
OIL & GAS DIV.
DIST. 237

18. I hereby certify that the foregoing is true and correct

SIGNED W. P. Mary
(This space for Federal or State office use)

TITLE Operations Manager

DATE 5/12/86

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:
SEE ATTACHED FOR
CONDITIONS OF APPROVAL

TITLE

APPROVED
AS AMENDED

DATE

JUN 12 1986

John Keller

AREA MANAGER

*See Instructions on Reverse Side

NMOC