



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
[http://nemrds.state.nm.us/ocd/District 11/3district.htm](http://nemrds.state.nm.us/ocd/District%2011/3district.htm)

MECHANICAL INTEGRITY TEST REPORT

(~~TA~~ or UIC)

Date of Test 9-17-02 Operator Pride Energy API # 30-0 43-20729

Property Name San-Isidro Well # 7-11 Location: Unit X Sec 7 Twn 20 Rge 2

Land Type:

State _____
Federal X _____
Private _____
Indian _____

Well Type:


Water Injection _____
Salt Water Disposal X _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____

TA Expires: _____

Casing Pres. 0 _____
Bradenhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____



Pressured annulus up to 418 psi. for 30 mins. Test passed failed

REMARKS:

No BH valve - operator will dig out + contact ocd for test. - Unable to inspect pump facility - operator reported that Murphy kill switch was broken - New one on order to be installed within a couple of day - Anthony Morales will send me a key + I will follow up to determine proper kill setting + operation.


By John C. Angel-Consultant
(Operator Representative)

Witness

Bruce Martin
(NMOCD)

(Position)

REVISED 11-17-98



GRAPHIC CONTROLS CORPORATION

CHART NO. MC MP 1000

METER

CHART PUT ON

1:15 P

LOCATION

REMARKS

Pride Energy
San Isidro #7-11

API 30-043-20729

K-7-20 N-02 W

9/17/2002

Jca

TAKEN OFF

1:45 PM

