

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.

**SUBMIT IN TRIPLICATE**

**RECEIVED**  
SEP 25 1998

**OIL CON. DIV.**  
DIST. 3

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
High Plains Petroleum

3. Address and Telephone No.  
3860 Carlock Dr., Boulder, CO 80303 303-494-4529

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
1900'FNL & 2250'FEL Section 26, T20N, R3W, NMPM

5. Lease Designation and Serial No.

NMNM 99702

6. If Indian, Allottee or Tribe Name

If Unit or CA, Agreement Designation

8. Well Name and No.

San Isidro #26-7

9. API Well No.

10. Field and Pool, or Exploratory Area

San Isidro Mesaverde

11. County or Parish, State

Sandoval County,  
New Mexico

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

**TYPE OF ACTION**

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Cleanup of a minor oil spill  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The contaminated soil from the spill was dug up by F.F. Construction and spread out to be land farmed on site, as instructed and as shown on the attached pictures, which were taken at the time the spill was discovered and then after it was cleaned up by High Plains.

14. I hereby certify that the foregoing is true and correct

Signed John B. Arnes II

Title Petroleum Engineer & Pres. Date 9/18/98

(This space for Federal or State office use)

Approved by Patricia M. Hester

Title Lands and Mineral Resources

Date 9/22/98

Conditions of approval, if any:

Oil Spill Discovered 4/27/98 at Jon Isidro #26-7,  
which came from Delhi-Trading's test tank.






Photo taken 8/18/98 by John Somers

Well and Tank Battery Site  
for

San Isidro #26-7

after

Cleanup of the oil spill  
by

FW Construction  
for

High Plains Petroleum