MERRION OIL & GAS CORPORATION

Jicarilla 430-9 2310' FSL and 660' FEL Sec. 36, T23N, R05W Sandoval County, New Mexico

SLOPE TESTS

Depth	Hole Deviation
225	1/2
717	3/4
1251	l
1782	1-1/4
2314	. 2
2620	1-1/2
3140	1-1/2
3720	1-1/4
4242	1-1/4
4785	1-1/4
5287	1-1/2
6095	2-1/4



		OIL 001985 D
State of New Mexico)	
County of San Juan) ss)	
I, <u>Steve S. Dunn</u> the above and forego to the best of my in	, being first du ping depth and hole deviat formation and belief.	ly sworn, depose and state that ion figures are true and correct
Subscribed and sworn	before me this2nd da	y ofOctober, 1985
	-	Notary Public

My Commission Expires . /