

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING
P. O. BOX 168
FARMINGTON, NEW MEXICO 87499
(505) 326-2659

NATANI #33
Sec. 1, T21N, R6W
790' FSL & 1450' FWL
Sandoval County, NM

SLOPE TEST

<u>Depth</u>	<u>Hole Deviation</u>
100'	0°
734'	$\frac{1}{4}^{\circ}$
970'	$\frac{1}{2}^{\circ}$
1390'	$\frac{1}{4}^{\circ}$
1729'	$\frac{1}{4}^{\circ}$
1879'	$\frac{1}{2}^{\circ}$

State of New Mexico)
) ss
County of San Juan)

NOV 25 1985
OIL CON. DIV.
DIST. 3

I, Robert L. Bayless, Operator, being first duly sworn,
depose and state that the above and foregoing depth and hole
deviation figures are true and correct to the best of my
information and belief.

Subscribed and sworn before me this 22nd day of November, 1985.

Eileen Hare
Notary Public

My Commission Expires

9-20-88