

J

30-043-20810

11-17-86

F. Loc. 1750/S; 890/W Elev. 6838 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @ T Gas
Csg. Perf. Prod. Stim.T
R
A
N
SBO/D 1st Del. Gas
MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NI TD X	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres 40								

P

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

Otero
Sanostee GalCo. SA S 9 T 22N R 4W UL Oper. Mallon Oil Co.

Lse. Jic. 435 G

No. 2

Jic. 435 G #2

L-9-22N-4W

MALLON OIL CO.

Jic. Cont. 435 (WC)
3162.3-1 (016)

Caller Service 4104
Farmington, New Mexico 87499

NOV 23 1987

CERTIFIED—RETURN RECEIPT REQUESTED
P-684-171-546

Mallon Oil Company
2850 Security Life Building
Denver, CO 80202

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) for well No. 2
Jicarilla 435 G, NW/4SW/4 sec. 9, T. 22 N., R. 4 W., Sandoval County, New
Mexico, Jicarilla Contract 435.

The subject APD is rescinded and returned due to drilling not being commenced
within one year of the approval date.

You are required to request surface rehabilitation instructions from this
office if construction activities occurred on the referenced drill site. If
this office does not receive comment within 30 days, we will presume that no
construction occurred. Later discovery that construction activities have in
fact occurred, may result in an assessment for noncompliance.

Sincerely,

/s/ John L. Keller

FOR: Ron Fellows
Area Manager

1 Enclosure

cc:
NMOCD

RECEIVED
NOV 30 1987
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION