

ROBERT L. BAYLESS

PETROLEUM PLAZA BUILDING  
P. O. BOX 168  
FARMINGTON, NEW MEXICO 87499  
(505) 326-2659

NATANI #27  
Section 3, T21N, R6W  
Rio Arriba County, New Mexico

SLOPE TEST

| <u>Depth</u> | <u>Hole Deviation</u><br><u>(Degrees)</u> |
|--------------|---|
| 95'          | 1/4                                       |
| 600'         | 1 1/4                                     |
| 985'         | 1   |
| 1380'        | 1 1/2                                     |
| 1760'        | 1 1/4                                     |
| 1875'        | 1   |

**RECEIVED**

MAY 27 1988

OIL CON. DIV.  
DIST. 3

State of New Mexico )  
County of San Juan ) ss

I, Kevin H. McCord, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

*Kevin H. McCord*

Kevin H. McCord  
Engineer

Subscribed and sworn before me this 26th day of May, 1988.

*Eden Hare*

Notary Public

My Commission Expires:

9/20/88