



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Albuquerque Field Office  
435 Montano Road, N.E.  
Albuquerque, New Mexico 87107  
www.nm.blm.gov

IN REPLY REFER TO:

NMSF081171K

3162.5-1 (b), Erin #2

OCT 11 2002

CERTIFIED--RETURN RECEIPT REQUESTED  
7000 1670 0009 0045 3776

Coulthurst Management Investment, Inc  
1990 Marin Avenue  
Berkeley, CA 94707

Dear Operator:

A recent inspection of the Erin #2 (30-043-08620), located in T. 18 N., R. 3 W., 990' FNL and 2310' FSL of Section 33, found your operations out of compliance with Onshore Order #7. Produced water is not being contained within the permitted earthen pits and is running out onto the landscape and into nearby surface drainages. This is a violation of your permit to dispose of produced water to an unlined pit.

All produced water must be contained within the unlined earthen pits by reconstruction. If this is not possible, another method of water disposal must be used.

This is a written order of the authorized officer and must be completed within 45 days from receipt of this letter. The receipt date will be considered the actual date of receipt or seven business days after notice is mailed. Under provisions of 43 CFR 3165.3, you may request an administrative review of the order described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice with the State Director, Bureau of Land Management, PO Box 27115 Santa Fe, NM 87501-7115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders and/or decisions are contained in 43 CFR 3175.4 and 43 CFR 4.400 et seq.

If you have any questions, please contact Patricia M. Hester at (505) 761-8786.

Sincerely,

Original Signed by

BRIAN DAVIS

for Steven W. Anderson  
Assistant Field Manager  
Division of Multi-Resources

cc: Attached