



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://nemrdd.state.nm.us/ocd/District/II/3district.htm>

MECHANICAL INTEGRITY TEST REPORT

(TA or MIE)

Date of Test 10-8-02 Operator Coulturst NGT API # 30-0 43-20869

Property Name Erin Well # 4 Location: Unit F Sec 13 Twn 18 Rge 3

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas ☒ _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): Y

TA Expires: 10-8-07

Casing Pres. _____
Bradenhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____


Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 500 psi. for 30 mins. Test passed/failed

REMARKS:

Packer set @ 299'



By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

REVISED 11-17-98

6 AM

7

8

9

Test En

GRAPHIC CONTROLS CORPORATION

CHART NO. MC MP-1000

METER


10/08/02

1:05pm

1:35p

Coulthurst MGT
Erin #4

API #30-043-20869
F. 13-18-3



RV

6 PM