

MERRION

OIL & GAS


MEU No. 9

Section 14, T19N, R3W
Sandoval County, New Mexico

SLOPE TESTS


<u>Depth</u>	<u>Hole Deviation</u>	<u>Depth</u>	<u>Hole Deviation</u>
#1 90'	0.75°	#8 2888'	0.5°
#2 248'	0.25°	#9 3390'	0.25°
#3 500'	1.0°	#10 3889'	1.5°
#4 1053'	1.0°	#11 4392'	0.75°
#5 1547'	1.5°	#12 4894'	0.75°
#6 2048'	1.25°	#13 5424'	1.5°
#7 2399'	0.75°		

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.


Steven S. Dunn

Subscribed and sworn before me this 12th day of March, 1997

State of New Mexico }
 } ss
County of San Juan }


Esther J. Greyeyes
Notary Public

My Commission Expires: August 7, 1998

