

# MERRION

OIL & GAS

RECEIVED  
FEB - 6 1997

## HAKUNA MATATA No. 1


Section 16, T20N, R4W  
Sandoval County, New Mexico

OIL CON. DIV.  
DIST. 3

### SLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>		<u>Depth</u>	<u>Hole Deviation</u>
#1	123'	1°	#8	3105'	1.75°
#2	342'	0.25°	#9	3604'	1.25°
#3	854'	1.75°	#10	4096'	2.5°
#4	1104'	1.25°	#11	4438'	1.25°
#5	1604'	1.5°	#12	4936'	1.5°
#6	2101'	1.25°	#13	5435'	2.0°
#7	2597'	1.25°	#14	5921'	0.75°
			#15	6447'	0.5°

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

  
Steven S. Dunn

Subscribed and sworn before me this 5th day of February, 1997

State of New Mexico      }  
                              } ss  
County of San Juan      }

  
Esther J. Greeyes  
Notary Public

My Commission Expires: August 7, 1998