



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078656-C

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

| | | | |
|--|----------|--|--|
| NOTICE OF INTENTION TO DRILL | | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | X | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 15, 1957, 19

Well No. 1 is located 2396 ft. from N line and 280 ft. from E line of sec. 22
SW 1/4 NW 1/4 22 18 N. 3 W. NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Terrejon Sandoval New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6588 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Fill with drilling mud, cement 20 ft. 4 inch pipe with
2 sacks cement as marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Clyde B. Harvey
 Address 439 Camino del Monte Sol
Santa Fe, New Mexico
 By C. B. Harvey
 Title Superintendent