

New Mexico

Land Office


Lease No. **DM 03829 A**

Unit

RECEIVED

1

Form 9-331a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U. S. GEOLOGICAL SURVEY
WASHINGTON, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29, 1960

Well No. 1 is located 367 ft. from N line and 330 ft. from E line of sec. 17

SE 1/4 SE 1/4

(1/4 Sec. and Sec. No.)

18 North 3 West

(Twp.) (Range)

N.N.P.M.

(Meridian)

New Mexico

(State or Territory)

Sandoval

(County or Subdivision)

(Field)

The elevation of the derrick floor above sea level is 6573 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded: June 8, 1959
Completed: June 20, 1959
P&A
Total Depth 1510' in gray
sandy shale
No show of oil or water

PLUGGING PROCEDURES:

Cemented from 1430 to 1485'
Cemented from 700 to 850'
Cemented from 500 to 625'
Cemented 10 sacks in casing to surface

No electric logs were run



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company W.W. Holmes, Operator

P.O. Box 367

Address Amarillo, Texas

By [Signature]
General Manager

Title _____

