



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Window Rock

Allottee Navajo Indian

Lease No. 14-20-601-523

Gulf Navajo "A"

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 12th, 1957

Well No. 1 is located 2310 ft. from N line and 1630 ft. from W line of sec. 4

22 1/4 NW 1/4 Sec. 4
(1/4 Sec. and Sec. No.)

21N 16W
(Twp.) (Range)

N.E.P.M.
(Meridian)

Wildcat
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5588 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11-22-55 TD 4005'. Spotted cement plugs as follows:

50 sacks from 3750' to 3600'
35 sacks from 3450' to 3300'
35 sacks from 2700' to 2550'
35 sacks from 950' to 780'
35 sacks from 80' to 50'

10 sacks in top of 9-5/8" surface casing, which was left in the hole.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BRIDGES-MONTIN-GRUBER DRILLING CORP.

Address 405 1/2 West Broadway

Farmington, New Mexico

By Albert R. Greer

Title Vice-President

