

(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Havas Indian

Lease No. 1-149-Ind-7170

Stony Butte #11

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 31st, 1958

Well No. 11 is located 950 ft. from [S] line and 605 ft. from [E] line of sec. 36
SE/4 SE/4 Sec. 36 22N 14W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Stony Butte San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6006 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1-31-58 TD 3975'. Spotted cement plugs as follows:

100 sacks 3975' to 3600'
 45 sacks 3600' to 2700'
 40 sacks 2700' to 1950'.

10-cush plug in top of 8-5/8" casing, which was left in the hole. Erected dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HENSON-MONTIN-OSHER DRILLING CORP.

Address 405 1/2 West Broadway

Farmington, New Mexico

By Albert R. Greer

Title Vice-President