

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo Indian

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Navajo Indian
Lease No. 1-149-2nd-TATG
Stony Butte #10

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

RECEIVED
SEP 5 1957

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) U. S. GEOLOGICAL SURVEY

September 3rd, 1957

FARMINGTON, NEW MEXICO

Well No. 10 is located 2420 ft. from S line and 1620 ft. from E line of sec. 36
NE 1/4 Sec. 36 (34 Sec. and Sec. No.) 24N (Twp.) 10W (Range) R.M.P.M. (Meridian)
Stony Butte (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6050 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Mass Verde test. Estimated total depth 1000'. It is proposed to set 5-1/2" 15.5# 2-75 casing through the pay zone, perforate 5-1/2" casing and sand-oil fracture, if commercial production is indicated. Cable tools will be used to drill the well.

RECEIVED
OIL SEP 6 1957

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BRUNSON-MARTIN-OWEN DRILLING CO.
Address 405 1/2 West Broadway
Farmington, New Mexico
By Albert R. Green
Title Vice-President

NEW MEXICO OIL CONSERVATION COMMISSION
Well Location and Acreage Dedication Plat

Section A.

Date September 3, 1957

BENSON-MONTIN-GREER DRILLING CORP.

Operator ~~XXXXXXXXXXXX~~ Lease STONY BUTTE
Well No. 10 Unit Letter J Section 36 Township 22 NORTH Range 14 WEST, NMPM
Located 2420 Feet From the SOUTH Line, 1650 Feet From the EAST Line
County SAN JUAN G. L. Elevation _____ Dedicated Acreage 40 Acres
Name of Producing Formation Mesa Verde Pool Stony Butte

1. Is the Operator the only owner* in the dedicated acreage outlined on the plat below?
Yes X No _____.
2. If the answer to question one is "no," have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes _____ No _____. If answer is "yes," Type of Consolidation _____
3. If the answer to question two is "no," list all the owners and their respective interests below:
TEM: 200' SE of Location. Elev: 6043.0

Owner


Land Description

RECEIVED

SEP 4 1957

U.S. DEPT. OF SURVEY
FARMINGTON, NEW MEXICO

Section B



This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

BENSON-MONTIN-GREER DRILLING
(Operator) **CORP.**

Alfred R. Greer
(Representative)

405 1/2 West Broadway

Address

Farmington, New Mexico

This is to certify that the well location shown on the plat in Section B was plotted from field notes of actual surveys made by me or under my supervision and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed 13 AUGUST 1957

James P. Leese
Registered Professional
Engineer and/or Land Surveyor.
James P. Leese

Certificate No. 1463