


(SUBMIT IN TRIPLICATE)

Indian Agency San Juan

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 1000



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent report of test</u>	<u>1</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SCOUTS CIRCLE UNIT

Farmington, New Mexico May 2, 19 57

Well No. 3 is located 1900 ft. from SW line and 990 ft. from [E] line of sec. 20

NE 1/4 of SE 1/4 Section 23

T-23-N

R-23-W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

New Mexico

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 1200 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5/2/57: DWT #1 from 1270-1331. 1" TC & 3/4" DC. 70 25 min. Fair blow at start to end at end of 35 min. Recovered 200' muddy water. 51 30 min. 25 0000, 70 0000, 71. 10. 2100. Chloride in ditch 200 ppm. in test 1000 ppm. Test satisfactory.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Mumble Oil & Refining Company

Address Box 1240

Farmington, New Mexico

COPY ORIGINAL
SIGNED: R. M. LILLY
By Harold E. Lilly
Title Dist. Eng.

