



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. S.F. 079097
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 23, 1958

Well No. 4 is located 1900 ft. from [N] line and 650 ft. from [E] line of sec. _____
SE 1/4 NE 1/4 Sec. 9 (1/4 Sec. and Sec. No.) 22 N (Twp.) 10 W (Range) N.M.P.M. (Meridian)
Wilcoat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6397 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud September 5, 1958

Set 100' 9-5/8" casing with 100 sacks. Pumped returns to surface.
Total 30 min. with 13 1/4 psi

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. B. LaRue, Jr.
Address First National Bank Bldg.
Box 209
Athens, Texas
By /s/ E. B. LaRue, Jr.
Title Operator