

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **SP-078653**

Lease No. _____

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	DST X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SOUTH CHACO UNIT

Parrrington, New Mexico June 28, 1957

Well No. **4** is located **1130** ft. from **[N]** line and **1130** ft. from **[E]** line of sec. **10**

NE/4 of NE/4

(1/4 Sec. and Sec. No.)

T-22-N

(Twp.)

R-8-W

(Range)

(Meridian)

Morrison W/C

(Field)

San Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is **6858** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6/27/57: DST #11 from 5689' - 5725', 1" TC, 3/4" BC. TO 1-1/2 hrs. Good blow thruout. Res. 60' slightly oil & gas cut mud, 2170' fresh water, chloride 450 PPM, IM 2800#, IP 20#, Max F 940#, BU after 30 min. 2100#, FM 2750#.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Humble Oil & Refining Company**

Address **Box 1268**

Parrrington, New Mexico

COPY ORIGINAL SIGNED **R. M. LILLY**

By **Russell M. Lilly**

Title **Dist. Supt.**