



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe, N.M.**

Lease No. **NM 04697**

Unit _____

RECEIVED
AUG 8 1957
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 6, 1957

Meyer Gov't
Well No. **3** is located **656.61** ft. from **SW** line and **2030.98** ft. from **W** line of sec. **20**

SW 20 (1/4 Sec. and Sec. No.) **23N** (Twp.) **11W** (Range) **10PM** (Meridian)
Wildcat (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation ~~of the well bottom~~ is **6173.67** ft. (Approx. ground)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

(Spudded 7-29-57)

7-29,30-57 Ran and cemented 8-5/8", 24#, J-55 casing at 176' with 190 sacks treated cement. Good returns to surface. Flanged up and waited on cement. Pressure tested BOP and casing with 700 psi. for 15 minutes, OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Shell Oil Company**

Address **101 South Behrend**

Farmington, New Mexico

By **B. W. Shepard**

Title **Exploitation Engineer**

