



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 32-079179-A
Unit _____
Co. Loc. No. 239550

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

TAMM UNIT

Farmington, New Mexico September 3, 1957

Well No. 2 is located 1980 ft. from NE line and 660 ft. from W line of sec. 23
SW/4 Section 23 T-23-N R-12-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Tanner Unit San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is later ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8/22/57: Spudded hole at 4:30 PM, 8/22/57.

8/29/57: Set 292' - 9-5/8" casing at 305' w/300 sacks neat w/3% cal. chl. cement. PCB at 7:20 AM, 8/28/57. Cement circ.

8/30/57: Drilled plug at 7:20 AM, 8/29/57.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

COPY ORIGINAL
SIGNED: R. M. LILLY

By Russell M. Lilly
Title Dist. Mgt.

AM/