



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 57-079179-A
Unit _____
Co. Lee. 239550

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY <u>DST</u>
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

TINNER UNIT

Farmington, New Mexico September 16, 19 57

Well No. 2 is located 1980 ft. from S line and 660 ft. from W line of sec. 23
SW/4 Section 23 T-23-N R-12-W (Meridian)
(1/4 Sec. and Sec. No.) (Twp.) (Range) New Mexico
Tinner Unit San Juan (County or Subdivision) (State or Territory)
(Field)

The elevation of the derrick floor above sea level is 6033 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9/12/57: DST #4 4440' - 4490', 1" TC & 5/8" BC. TO 1 hr. Strong blow. Res 144' EX OCCM & 2116' salt water. IM 2265, min. fl. 250#, max fl. 335#, FF 2265#, 30 min BU 2135#.
9/14/57: DST #5 4519' - 4571', 1" TC & 5/8" BC. TO 1 hr. Strong blow. Res 180' OCCM, 970' SOLGCCW. IM 2380, min. & max fl. 15# & 435#, FN 2095, 30 min BU 2350#. (Dakot.)
DST #6 3540' - 3555', 1" TC & 5/8" BC (Straddle Packer) TO 1 hr. Fair blow, weakened & died in 50 min. Res 50' drlg. mud. IM 1805#, min & max fl. 15#, FN 15#, 30 min. BU 1775#. (Gallup).
9/16/57: DST #7 4585' - 4720' w/1" TC & 5/8" BC. TO 47 min. Salt water to surface in 27 min. Flowed at rate of approx 25 gals./min. Initial mud 2365, min. fl. 1050#, max 2065#. Final 2365, BU after 30 min - 2155.

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Rumble Oil & Refining Company
Box 2168
Address Farmington, New Mexico

COPY ORIGINAL
SIGNED: R. M. LILLY

By Russell M. Lilly
Dist. Supt.

Title

AW/