



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SF 378847  
Unit Chaco Unit # 14-08-001-  
2026

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED  
AUG 11 1958

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 21, 1958

Well No. 3 is located 2012 ft. from [N] line and 2016 ft. from [E] line of sec. 21

NE/4 Sec. 21 23N 8W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilcoast San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6800 ft. Ground

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

We plan to pull 3400' of 7-1/2" casing, placing cement plugs as follows:  
(The hole was 7-7/8"), 4740 - 4940' with 60 sacks, 3760 - 3910' with 50 sacks,  
1965 - 2115' with 50 sacks, 1220 - 1370' with 50 sacks, 275 - 155 with 35 sacks  
and 10 sacks in the top of the 9-5/8" surface pipe. The location will be properly  
cleaned and a marker properly placed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Devis Oil Co.  
Address 802 Midland Savings Bldg.  
Denver, Colo.

By Paul Messinger  
Title Expl. Mgr. Southern Div.