

U. S. LAND OFFICE *Navajo Allotted*
SERIAL NUMBER _____
LEASE OR PERMIT TO PROSPECT _____
Lease #1-149-IND-8113
Chaco Unit #14-08-001-2026
THE INTERIOR
SURVEY

LOCATE WELL CORRECTLY

The information given herewith is a complete and correct record of the wall and all work done thereon so far as can be determined from all available records.

The summary on this page is for the condition of the well at above date.

Commenced drilling March 10, 1955 Finished drilling April 1, 1955

(Denote gas by G)

to
to
to
JUN 27 1955
OIL CON. COM.
DIST. 3
to

No. 1, from 5537 to 5822 No. 3, from _____ to _____
No. 2, from _____ to _____ No. 4, from _____ to _____

[illegible]

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
10-3/4	206	200	Pump	Water	---
5 1/2	1619	275	Pump	9.1	

Heaving plug—Material Length Depth set

Adapters—Material Size

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
3½	4" (107')	100% SNG	270	4-16-55	1663 to 4770	4770
	Axidized 8	5924 oil frs.	4619	4770		

Rotary tools were used from _____ feet to 5830 feet, and from _____ feet to _____ feet
Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet.

----- **May 10** -----, 19- **55** Put to producing ----- **May 17** -----, 19- **55**
 The production for the first 24 hours was ----- **60** ----- barrels of fluid of which ----- **100** ----- % was oil; ----- %
 emulsion; ----- % water; and ----- % sediment. Gravity, °Bé. ----- **37.5° API** -----

If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

_____, Driller _____, Driller
_____, Driller _____, Driller

FROM—	TO—	TOTAL FEET	FORMATION
TOPS			
1090			Pictured Cliffs
1453			Mesa Verde
2524			Cliff House
2621			Menefee
3532			Point Lookout
3650			Mancos
4630			Tosito
5145			Sanastee
5440			Green Horn
5501			Graneros
5537			Dakota
5828			Morrison
T.D. 5830	PB 4770		

[illegible]