



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Approval expires 12-31-60.
Indian Agency Window Rock, Ariz.

Allottee _____
Lease No. 1-149-Ind. 8111-4

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
APR 10 1958
U.S. GEOLOGICAL SURVEY
FAC. DIVISION, 1925

Well No. 6 Chaco Unit is located 1900 ft. from S line and 660 ft. from W line of sec. 12
C. M. S. Sec. 12 (1/4 Sec. and Sec. No.) T23N (Twp.) 3W (Range) N.M.P.M. (Meridian)
Wildest (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6762 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The following cement plugs will be set:

- 5 sacks at surface
- 50 sacks 750 to 900 feet.
- 50 sacks 1500 to 1650 feet.
- 50 sacks 3700 to 3850 feet.
- 50 sacks 4650 to 4800 feet.
- 50 sacks 5550 to 5750 feet.

RECEIVED
APR 14 1958
CON. COM.
ST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVIS OIL COMPANY
Address 1020 Midland Savings Building
Denver, Colorado

By Paul Messinger
Title Exploration Manager-Southern Div.