



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R359.4.
Approval expires 12-31-60.

Indian Agency Window Rock
Arizona
Allottee _____
Lease No. 1-140-Ind.-0111-A

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	XX
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ILLEGIBLE

June 4, 1958

Well No. 6 CHACO is located 1900 ft. from 1/4 line and 600 ft. from W line of sec. 12

1/4 3/4 Sec. 12 (1/4 Sec. and Sec. No.) T 23 N - R 9 W (Twp.) (Range) 104°N (Meridian)
Wilcox (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6763 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate sanding, cementing points, and all other important proposed work)

The following cement plugs were set:

Sacks
5 at surface
50 from 750' to 900'
50 from 1500' to 1650'
50 from 3700' to 3850'
50 from 4650' to 4800'
50 from 5500' to 5750'

Pits filled, location cleaned and graded, and marker created. It is now ready for your inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVIS OIL COMPANY

Address 1020 Midland Savings Bldg.

Denver 2, Colorado

By Paul Messinger
Paul Messinger
Title Exploration Manager, Southern Div.