

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **SF-079718**

Lease No. _____

Unit **NAM**

Co. Loc. #216951

JAN 27 1958

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

TANNER UNIT

Farmington, New Mexico January 26, 1958

Well No. **3** is located **660** ft. from **N** line and **660** ft. from **E** line of sec. **5**

NE/4 Sect. 5

T-23-N

R-12-W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Dakota Sand Wildcat

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)


The elevation of the derrick floor above sea level is **5994** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Placed cement plugs as follows:

4942', back to 4840' w/35 sz.
4750', back to 4550' w/72 sz.
3750', back to 3650' w/35 sz.
2750' back to 2610' w/53 sz.



Cellar and pits were filled, location leveled and all junk and surface equipment was removed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Humble Oil & Refining Company**

Address **Box 1268**

Farmington, New Mexico

By **Russell M. Lilly**
Russell M. Lilly
Title **Dist. Supt.**