

Santa Fe Leggs #1 -

1. Open water tank which was unsafe to gauge due to corrosion revealed 42" asphaltic oil which ~~will be~~ hauled to recycler
2. Material under sump in cement floor of pump house ~~will be~~ excavated and landfarmed.
3. Hydrocarbon contamination was found on water pit which ~~will be~~ excavated and landfarmed
4. Land farm ~~will be~~ disced and sampled.

Marcelina #1/E

1. Sampling pit revealed contamination which must be ~~excavated~~ excavated, landfarmed, ~~disced~~ and sampled for clearance.

~~2~~

Ballseye #5

1. Sampling pit revealed contamination which must be excavated, landfarmed, disced and sampled

Ballseye main Battery

1. Sampling contamination under tanks and sampling drain pit revealed volumes of contamination which must be ~~excavated~~ excavated, landfarmed, disced and sampled. Due to volumes some material will be transferred to the Ballseye #7 location.