

FIELD INSPECTION FORM FOR WELLS TO BE PLUGGED

DATE INSPECTED 5-7-98

BY Raun Smith

OPERATOR: APA Development Inc

PROPERTY NAME & #: Leggs

FOOTAGE: 990 FSL 2310 FWL

LOCATION: UL: N SEC: 11 TWN: 21N ROE: 10W

POOL/S: Leggs Entrada

API# 30-045-23027

WERE PHOTOGRAPHS TAKEN? yes

NUMBER: 2

DESCRIPTION OF SUBJECT ON PHOTOGRAPH: _____

INVENTORY

DESCRIPTION OF WELLHEAD: Haber Hercules Flange type with 5" ports
2-5" plug Ball Valves, 2" check, 1 3" Plug valve, 1 3" check
various connections

SURFACE: 9 5/8

INTERMEDIATE: —

PROD CSG: 7"

TBG: 2 7/8 upset

RODS: none

PRODUCTION EQUIPMENT: _____

TANKS: 1- gasoline storage tank
no anchors

DESCRIPTION OF PITS

none