

FIELD INSPECTION FORM FOR WELLS TO BE PLUGGED

DATE INSPECTED 5-7-98 BY Ray Smith
OPERATOR: APA Development Inc PROPERTY NAME & #: Santa Fe Leggs
FOOTAGE: 990 FSL 2310 FEL LOCATION: UL: 0 SEC: 11 TWN: 21N RGE: 10W
POOLS: Leggs Entrada API# 30-045-22037
WERE PHOTOGRAPHS TAKEN? yes NUMBER: 1
DESCRIPTION OF SUBJECT ON PHOTOGRAPH: _____

INVENTORY

DESCRIPTION OF WELLHEAD: 2" flange type Hercules
3" wheally check valve, 1-2" check valve & various fittings

SURFACE: 95/8" INTERMEDIATE: _____ PROD CSO: 7"

TBG: 3" upset RODS: none

PRODUCTION EQUIPMENT: 1-3" Testamann Corp 1000 LB WP Plug Valve
2 1/2" Hercules Hercules Pumping Unit

TANKS: 1- 500 lbt painted. No name or numbers

4- 400 lbt American Tanks S/N'S 6893, 6896, 5488 + 5454

2- triph type pumps. One has an electric motor. The other one has none.

1- 25' x 40 Morgan type metal bldg

1- single drum double pole pulling Unit

1- National brand 50 LB WP. 22. round #1

DESCRIPTION OF PITS

1 30 x 40 yd pit. Pit is empty & fenced.