

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. M 8902
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE, OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 208, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL - 1770' FEL		8. FARM OR LEASE NAME Billie
14. PERMIT NO.		9. WELL NO. #1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6645' GR		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec 35 T22N R8W
		12. COUNTY OR PARISH San Juan
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
PLUG OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☒
ABANDON*	☐	ABANDONMENT*	☒
CHANGE PLANS	☐		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 4-6-82 Plugged and abandoned this well in the following manner:
1. Filled 2-7/8" O.D., 6.5#, J-55, 8 Rd, EUE tubing for casing from T.D. 900' to surface using 25 sx of cement.
 2. Modified plugging program with braden head squeeze using 26 sx of cement to fill the 2-7/8" casing annulus to an approximate depth of 220'.
 3. Installed permanent dry hole monument.
 4. Filled all pits.
 5. Cleaned well location of all equipment, pipe, junk, and trash.
 6. Restored surface; will reseed next planting season.
 7. Cut off tie-downs.

RECEIVED
JUL 7 - 1983
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE Agent DATE 4-8-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: