UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

| Form 9-331 Dec. 1973 | Form Approved. Budget Bureau No. 42-R1424 | |
|--|---|--|
| UNITED STATES | 5. LEASE | |
| DEPARTMENT OF THE INTERIOR | NM-19569 | |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.) | 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME | |
| 1. oil gas well other Plugged & Abandoned | Tsaya 9. WELL NO. | |
| 2. NAME OF OPERATOR | 2 | |
| Southland Royalty Company 3. ADDRESS OF OPERATOR | 10. FIELD OR WILDCAT NAME Wildcat Alakala | |
| P.O. Drawer 570, Farmington, New Mexico | 11. SEC., T., R., M., OR BLK. AND SURVEY OR | |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 155' FNL & 1115' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: | AREA Description 4, T22N, R12W 12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO. | |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) | |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 6170' GR | |
| TEST WATER SHUT-OFF | (NOTE: Report results of multiple completion or zone change on Form 9–330.) | |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent | rectionally drilled, give subsurface locations and | |

"Re-seeding has been completed as per stipulations."



| | | | The state of the s | |
|---|--|------|--|----|
| Subsurface Safety Valve: Manu. and Typ | pe | | Set @ | Ft |
| 18. I hereby certify that the foregoing is | true and correct | DATE | February 8, 1982 | |
| APPROVED BY CONDITIONS OF APPROVAL, IF ANY: | (This space for Federal or State office us | -, | ACCEPTED FOR RECO | RD |

FEB 12 1982