

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1, oil well ☒ gas well ☐ other

2. NAME OF OPERATOR
Champlin Petroleum Company

3. ADDRESS OF OPERATOR
P. O. Box 1257, Englewood, CO 80150

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
 FRACTURE TREAT ☐
 SHOOT OR ACIDIZE ☐
 REPAIR WELL ☐
 PULL OR ALTER CASING ☐
 MULTIPLE COMPLETE ☐
 CHANGE ZONES ☐
 ABANDON* ☐
 (other) Name change

SUBSEQUENT REPORT OF:

000000

RECEIVED

OCT 11 1963

(NOTE: Report results of multiple completion or change on Form 3-330.)

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

02720 1933

W. C. C. 34.

~~DIST. 3~~

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

* The proposed #1 Federal 22-12 well is located within an area which was approved as a Federal unit on 9-28-83. It is requested that the name of this well be changed to the #2 Pueblo Bonito Federal Unit 22-12.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ramona J. Rhoden TITLE Sr. Eng. Aide DATE 10-5-83
Ramona J. Rhoden ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE OCT 10 1969
CONDITIONS OF APPROVAL IF ANY: _____

FARMINGTON RESOURCE AREA

BY: JMK

MMOC

4 Same change
was never reported
on I.D-B. So
abandonment reported
as originally permitted.

Lillian