

MERRION OIL & GAS CORPORATION

610 REILLY AVE. • P. O. Box 840

FARMINGTON, NEW MEXICO 87499

MERRION OIL & GAS CORPORATION

SANTA FE 20 NO. 4

Sec. 20, T21N, R8W
San Juan County, New Mexico

SLOPE TESTS

<u>Depth</u>	<u>Hole Deviation</u>
95'	1/2°
214'	1-1/4°
464'	3/4°
866'	1°
1,179'	1°
1,749'	1-3/4°
2,042'	1°
2,542'	1°
3,042'	2-1/2°
3,074'	2-1/2°
3,230'	1-1/4°
5,095'	1°

RECEIVED
SEP 26 1991
CON. DIV.
DIST. 3

State of New Mexico }
 } ss
County of San Juan }

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Lesa L. Sullivan

Subscribed and sworn before me this 23rd day of September, 1991.

Lesa L. Sullivan
Notary Public

My Commission Expires: August 7, 1994