

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Leave blank for use on reverse side)

5. LEASE DESIGNATION AND SERIAL NO.

NM-32124

6. IS INDIAN ALLOTTEE OR TRIBE LAND?

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P.O. Box 420, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660' FNL & 1980' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Calgary

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

South Bisti Gallup Ext.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 6, T23N, R10W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6555' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Spud & Surface Casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in and rigged up Four Corners Drilling Company rig #5. Spudded a 12-1/4" hole @ 9:15 AM 7-28-89. Drilled to 218'. Ran 5 jts. 8-5/8" OD, 24#, 8 Rd., ST&C casing (T.E. 201.16') set @ 212' RKB. Cemented with 135 sx class "B" + 2% CaCl₂ (total cement slurry = 159 cu.ft.). P.O.B. @ 12:45 P.M. 7-28-89. Circulated 4 bbls cement to surface. Pressure tested 600 psi for 30 minutes before drilling out - OK.

RECEIVED

AUG 15 1989

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim I. Jacobs

TITLE Geologist

DATE 7-31-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 15 1989

FARMINGTON DIST. LAND AREA

*See Instructions on Reverse Side