

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Drilling Company

3. ADDRESS OF OPERATOR

105 S. 4th St. Gallup, NM 88301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

400' FNL & 900' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6758' KB

5. LEASE DESIGNATION AND SERIAL NO.

NM-36949

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hurricane Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat - Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24-23N-9W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud Well

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-28-89 Spudded 12 1/4" hole at 11:15 am with Walter's Drilling Company rig. Ran 7 jts. 8 5/8", 24# J-55 casing set at 277'. Texas patterned notched guide shoe set at 277', insert float set at 234'. Cemented with 180 sxs. Class "B" + 3% CaCl + 1/4# sx. Flocele. PD at 4:00 pm, 7-28-89. Bumped plug to 1000 psi, float held okay. Circulated 50 sxs. cement. Nipped up and tested to 600 psi for 30 min., okay. Reduced hole to 7 7/8" and drilled out at 4:00 am, 7-29-89.

18. I hereby certify that the foregoing is true and correct

SIGNED Karen J. Leishman

TITLE Production Clerk

DATE 8-3-89

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE AUG 14 1989

FARMINGTON RESOURCE AREA

NMOCD

*See Instructions on Reverse Side