

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR BCO, Inc.		3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, NM 87501		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL & 660' FWL		5. LEASE DESIGNATION AND SERIAL NO. NM-8005		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
14. PERMIT NO.		15. ELEVATIONS (Show whether OF, RT, GR, etc.) GL 6730'		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Federal D		9. WELL NO. 6		10. FIELD AND POOL, OR WILDCAT South Bisti Gallup Ext	
						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 10 T23N R9W NMPM		12. COUNTY OR PARISH San Juan		13. STATE NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other) Submit temperature survey report	☒		
(Other)	☐			(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2/28/91

I submit a copy of the Temperature Survey run on this well when cement failed to circulate. This report establishes the cement top as 1070'. The 8 5/8" casing was landed at 365' and cement circulated. Also intend to run bond log over this interval to confirm cement top.

RECEIVED
APR 08 1991
ON COMPLETION
DISTRICT

ACCEPTED FOR RECORD
APR 01 1991
FARMINGTON RESOURCE AREA
BY

18. I hereby certify that the foregoing is true and correct
SIGNED Elizabeth B. Keeshan TITLE President DATE 2/28/91

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MIDLAND, TEXAS / FARMINGTON, NEW MEXICO
GRAND JUNCTION, COLORADO

reservoir engineering data

**P. O. Box 5278
Midland, Texas 79704-5278
(915) 682-5574**

**Midland Fax (915) 682-5329
Farmington Fax (505) 325-1148
Grand Junction Fax (303) 241-7634**

February 20, 1991

BCO, Inc.
135 Grant Avenue
Santa Fe, New Mexico 87501

Attention: Ms. Elizabeth Keesham

Subject: Temperature Survey
Federal "D" No. 6
San Juan County, New Mexico
File No. 2-22699-TS

Dear Ms. Keesham:

Attached hereto are the results of a temperature survey which was conducted on the above captioned well February 19, 1991.

The data presented are in graphical form.

It has been our pleasure to have conducted this service for you. If we may be of further assistance, please call us at any time.


Respectfully submitted,

TEFTELLER, INC.


Neil Tefteller

Neil Tefteller

NT/lw



TEMPERATURE SURVEY LOG



COMPANY BCO, INC.
 LEASE FEDERAL "D" WELL NO. 6
 FIELD _____
 COUNTY SAN JUAN STATE NEW MEXICO
 CASING SIZE _____ SET @ _____
 HOLE SIZE _____ TO _____
 CEMENT _____
 PLUG DOWN _____ TIME 1430
 SURVEY RUN _____ TIME _____
 TOP OF CEMENT 1070'
 TOTAL DEPTH RECORDED 4790'
 RECORDED BY _____
 REMARKS _____

RECEIVED
 APR 08 1991
 OIL CON. DIV.
 (1515)