

MERRION OIL & GAS CORPORATION

SANTA FE 20 NO. 5

Sec. 20, T21N, R8W  
San Juan County, New Mexico

SLOPE TESTS

<u>Depth</u>	<u>Hole Deviation</u>
263'	1°
747'	3-1/4°
837'	3-1/4°
961'	2-3/4°
1,180'	3-1/8°
1,393'	2-3/4°
1,601'	3-1/4°
1,801'	3-1/2°
1,895'	3-1/8°
1,990'	2-3/4°
2,115'	2-1/2°
2,241'	2-1/8°
2,395'	2-1/2°
2,519'	2°
2,644'	1-3/4°
2,738'	2°
2,832'	2°
2,925'	2°
3,050'	1-1/2°
3,144'	1-1/8°
3,423'	1°
3,768'	3/4°
3,956'	3/4°
4,052'	1°
4,423'	1°
4,701'	3/4°
5,197'	1-1/2°
5,625'	1°

**RECEIVED**  
JUL 19 1991  
OIL CON. DIV.  
DIST. 3

State of New Mexico }  
                              } ss  
County of San Juan }

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.



Subscribed and sworn before me this 11th day of July.

Lesa L. Sullivan  
Notary Public

My Commission Expires: August 7, 1994