

MERRION OIL & GAS CORPORATION

610 REILLY AVE. • P. O. Box 840
FARMINGTON, NEW MEXICO 87499

ESCOVADA NO. 1

Section 8, T21N, R8W
990' FSL & 1900' FWL
San Juan County, New Mexico

CONFIDENTIAL

SLOPE TESTS

<u>DEPTH</u>	<u>HOLE DEVIATION</u>	<u>DEPTH</u>	<u>HOLE DEVIATION</u>
270'	1/2°	4457'	4°
480'	1°	4476'	3-1/2°
698'	1-3/4°	4527'	3-3/4°
912'	1-1/2°	4571'	3-3/4°
1131'	1-1/2°	4632'	3°
1320'	1°	4666'	3°
1659'	1°	4726'	3°
2065'	1°	4788'	3-1/4°
2502'	1°	4855'	2-3/4°
3062'	1-1/4°	4914'	2-3/4°
3555'	1-1/2°	4977'	2-3/4°
3700'	1°	5070'	2-3/4°
4071'	1-1/4°	5226'	2°
4200'	3°	5440'	1-3/4°
4445'	3-3/4°	5968'	3/4°

State of New Mexico }
County of San Juan } ss

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

and correct to the best of my info

Subscribed and sworn before me this 22nd day of January, 1992.

Esther J. Greyeyes
Notary Public

My Commission Expires: August 7, 1994