

## MERRION OIL &amp; GAS CORPORATION

610 REILLY AVE. • P. O. Box 840



FARMINGTON, NEW MEXICO 87499

SANTA FE LEGGS NO. 3Sec. 11, T21N, R10W  
San Juan County, New MexicoSLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>
#1	260'	3/4°
#2	767'	1°
#3	1,260'	1-1/8°
#4	1,789'	1°
#5	2,070'	3/4°
#6	2,570'	1/4°
#7	3,067'	1/4°
#8	3,565'	3/4°
#9	4,057'	1/2°
#10	4,214'	1/2°
#11	4,716'	1/4°
#12	5,211'	1/2°
#13	5,662'	1°

**RECEIVED**  
JUN 10 1992  
OIL CON. DIV.  
DIST. 3State of New Mexico }  
                              } ss  
County of San Juan }

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

  
Steven S. DunnSubscribed and sworn before me this 9th day of June, 1992.  
Esther J. Greyeyes  
Notary Public

My Commission Expires: August 7, 1994