

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Rio Chama Petroleum, Inc.

3. Address and Telephone No.

P. O. Box 23553, Santa Fe, NM 87502, (505) 986 9723

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

D - Section 32 - T24N - R01W

5. Lease Designation and Serial No.

NM 036224

6. If Indian, Allottee or Tribe Name

N/A

7. If Unit or C/A, Agreement Designation

N/A

8. Well Name and No.

Crane Federal 3

9. API Well No.

30 - 039 - 05262

10. Field and Pool, or Exploratory Area

Blanco P.C. South

11. County or Parish, State

Rio Arriba County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recompletion of the Gas Well to a Water Supply was completed on April 21, 1994 as per the attached procedure.

RECEIVED
FEB 17 1993

OIL CON. DIV.
DIST. 3

ACCEPTED FOR RECORD

14. I hereby certify that the foregoing is true and correct

Signed

President

Date

1/26/98

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

**RIO CHAMA PETROLEUM
CRANE FEDERAL 3
D - Sec. 32 – T24N – R01W
Rio Arriba County, New Mexico**

1. Set CIBP at 3367'. Dumped 3 sx cement on top. Tested plug to 500 psi for 15 minutes. Held OK.
2. Perf 4 sqz holes at 3150' and sqzd with 100 sx Class 'B' cement. Tested sqz to 1300 psi for 12 minutes. Held OK.
3. Clean out hole to 3357'. Pressure tested to 500 psi for 15 minutes. Held OK. Test witnessed by Ernie Burch, NM OCD.
4. Perf OJO Alamo 3235' – 3252' with 4 jspf. Acidized perfs with 1,000 gals 15% HCL.
5. Swabbed water well in and put on pump.