

Section 27

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office 1011 10Lease No. 37-102

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 25, 1957

Well No. 1 is located 280 ft. from [N] line and 1700 ft. from [E] line of sec. 273-1 of Sec. 27

(1/4 Sec. and Sec. No.)

T-24-N

(Twp.)

R-7-E

(Range)

(Meridian)

Wilcat

(Field)

Rio Arriba County

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 7022 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Federal 1-27 #1 was spudded on February 20, 1957.
On February 22, 1957, 9 5/8", 30w surface casing was cemented
at 125 ft. with 350 sacks of regular port cement.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of TexasAddress P.O. Box 1917Houston 1, TexasBy Roy M. DickmanTitle General Engineer