



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 080500
Unit Anderson "A"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>Production</u>	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of Squeeze Jobs 1, 2, 3, 4 & 5</u>		<u>X</u>
	<u>Report of Perforations</u>		<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 15, 1958

Anderson "A"
Well No. 2 is located 990 ft. from S line and 990 ft. from E line of sec. 29
SE 1/4 Section 25 24N 2W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated (Pictured Cliffs) Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7535 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run & set $5\frac{1}{2}$ " casing at 3440' & cemented with 90 sks. reg. cement 25 gal, 90 cu. ft. Stratacrete. Run temperature survey by B&B Service Co. & found top of cement behind $5\frac{1}{2}$ " casing at 3200'.

Perforated $5\frac{1}{2}$ " casing 3399-3400' with 4 Walox jet shots.

SQUEEZE JOB NO. 1 - Casing Perfs. 3399-3400': Squeezed w/100 sks. reg. cement. BDP 900#, Max. Press. 900#, Min. Press. 0#, Standing Press. 0#.

SQUEEZE JOB NO. 2 - Casing Perfs. 3399-3400': Squeezed w/100 sks. Fomix & 100 sks. reg. cement 25 CaCl. BDP 1200#.

SQUEEZE JOB NO. 3 - Casing Perfs. 3399-3400': Squeezed w/100 sks. Fomix & 100 sks. reg. cement 25 CaCl. BDP 1200#

(CONT. ON BACK)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY
Box 426
Address Parlington, New Mexico

By _____
Title District Superintendent

SCUMMER JOB NO. 4 - Casing Perfs. 3399-3400'; Squeezed w/45 sks. reg. cement, 6% gel, 1% Flo-seal. Backwashed w/ 5 sks. reg. cement. BDP 1200#, Max. Press. 3500#, Min. Press. 1200#, Squeeze Press. 3500#, Standing Press. 3500#.

SCUMMER JOB NO. 5 - Casing Perfs. 3318-3319'; Squeezed w/46 sks. reg. cement w/6% gel & 1% Flo-Seal. Backwashed 4 sks. reg. cement. BDP 1400#, Max. Press. 3500#, Min. Press. 900#, Standing Press. 3500#.