न्द्रों । 19	7		DISIL 8
			OIL COM. DIN
			SEP 1 2 1997
	See attached for workover pr	ocedure.	ne de la
			وورد المراجع والمراجع والمستقل
13. Descri work.	be Proposed or Completed Operations (Clearly state If well is directionally drilled, give subsurface loca	all pertinent details, and give pertinent dates, incl tions and measured and true vertical depths for all	uding estimated date of starting any proposed markers and zones pertinent to this work.)*
		Other Workovers	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	Subsequent Report Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection
	Notice of Intent	Abandonment Recompletion Plugging Back	Change of Plans New Construction Non-Routine Fracturing
	TYPE OF SUBMISSION	TYPE OF A	CTION
12.	CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE	L F, REPORT, OR OTHER DATA
	Unit B, Sec 28 - 24N - 1W		Rio Arriba County, NM
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Blanco P. C. South 11. County or Parish, State
P. O. Box 23553, Santa Fe, NM 87502, (505) 986 9723			10. Field and Pool, or Exploratory Area
3. Address and Telephone No.			30 - 039 - 05320
Rio Chama Petroleum, Inc.			Harrington Federal #3 9. API Well No.
Oil Well Gas Well Other 2. Name of Operator			8. Well Name and No.
1. Type of W	ell	·	N/A
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
Do not u	SUNDRY NOTICES AND se this form for proposals to drill or to dee Use "APPLICATION FOR PI	pen or reentry to a different reservoir	NM SF 079352A 6. If Indian, Allottee or Tribe Name N / A
4*	DEPARTMENT U BUREAU OF LANI	STATES F THE INTERIOR D MANAGEMENT	Budget Burcau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Chief, Lands and Mineral Resources

SEP 1 1 1997

Date

(This space for Vederal or State office use)

Approved by/1

Conditions of approval, if any:

Title

RIO CHAMA PETROLEUM HARRINGTON FEDERAL #3 Repair Report

AUGUST 13, 1997

MI & RUSU. RIH with 3 7/8" bit and scraper.

AUGUST 14, 1997

Tag at 3008' KB. RIH and set RBP at 2956' KB (Fluid level 1040'). RIH with packer, tubing to 2943' KB. Test tubing and RBP to 500 psig. RIH with perforating gun and perforate 4 shots at 2890' KB. RIH with tubing and packer to 2627' KB. Squeeze with 100 sacks Class G +2% CaCl cement.

AUGUST 15, 1997

Pressure tubing to 500 psig for 5 minutes. Run in hole. Tag cement at 2482' KB. Drill cement from 2482' to 2679'. From 2679' to 2890'. Circulate hole clean at 2901'. Pressure casing to 500 psig.

AUGUST 16, 1997

Run in hole. Release RBP and pull out of hole. Run in hole with 95 joints (2998.30') 2 3/8" tubing. Tag PBTD at 3015' KB. Rig up to swab. Made twenty swab runs. Recovered 45 bbls. water. Final fluid level – 2700'. Final casing pressure – 0 psig. Shut down operations.