


Form 9-281a
(Feb. 1961)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 01330
Unit Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Water Frac.</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 10, 1961

Well No. 29-2 is located 500 ft. from N line and 1000 ft. from W line of sec. 2

Sec. 2 (1/4 Sec. and Sec. No.) 24N (Twp.) 25 (Range) N.M. (Meridian)


Wilcox (Field) New Mexico (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7422 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-10-50 C.O.T.D. 3465'. Water fractured fractured Cliffs perf. Int. (2 1/2"/ft. 3300-3600; 3400-20; w/ 35,300 gallons water and 35,000 sand. Max. pr. 3200, avg. tr. pr. 1500, 2000, 2300, 3200. I.R. 46.0 Min. Flush 3000 gallons. 25 Gall mixed w/frac. water. 4 stages - 3 drops of 20 balls.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Gas Corporation

Address Box 997

Farmington, New Mexico

By ORIGINAL SIGNED E.S. OBERLY

Title Agent