

DIRECTOR JOE D. RAMEY

OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO 1000 RIO BRAZOS RD. - AZTEC

> 87410 LAND COMMISSIONER PHIL R. LUCERO



EMERY C. ARNOLD

September 14, 1977

Continental Oil Company 501 Airport Drive Farmington, New Mexico 87401

Re: AXI Apache D #2 N-19-24N-4W Dear Mr. Anderson,

The attached bradenhead test report for the subject well indicates communication between the casing and the annulus.

You are hereby directed to take immediate action to cause the well to comply with Rule 108 and proceed with diligence to use the appropriate method and eliminate such hazard of underground waste.

If there are questions, please contact us.

Yours very truly,

M. E. Malwell

N. E. Maxwell, Jr. Engineer, District #3

Attachment

xc w/ attachment: Oil Conservation Commission

Santa Fe, New Mexico 87501

NEM:no

NEW MEXICO OIL CONSERVATION COMMISSION 1000 Rio Brazos Road Aztec, New Mexico

Retest BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	e de la companya del companya de la companya del companya de la co
Date of Test 9-13-77 Operator C	ONOCO
Lease Name AXT APAche Divell No.	Q Location UN Sec. 19 Twp 24N Rge. 4W
Pressure (Shut-in or Flowing) Dwt. Tubing	Casing 184 Bradenhead 184
OPEN BRADENHEAD TO ATMOSPHERE FOR 1	5 MINUTES.
Casing or Tubing Pressure, Dwt.	Bradenhead Flowed:
5 Min	Steady Flow
10 Min. 182	Surges
15 Min	Down to Nothing
20 Min. 179	Nothing
25 Min	Gas
30 Min	Gas & Water
40 min 175	Water
If Bradenhead flowed water check description belo	w:
Clear	Remarks: BRADENLEAD MAKING 110
Fresh	MCF/D AFTER 15 min = /10 MCF
Sal ty	AFTER 30 MIN.
Sulfur	
Black	
	By Deuris L. Moore
	Position
	Witness Murlo Molson