



3-uses
1-Reese
1-Eastern
1-Phillips
1-File

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

Land Office Santa Fe

Lease No. N.M. 014021

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Free	XI

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 2, 1958

Well No. Federal 1-22 is located 660 ft. from EX line and 1980 ft. from EX line of sec. 22
SE 1/4 SW 1/4 Sec 22 24N 7W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Escrito-Gallup Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground level ~~XXXXXXXX~~ above sea level is 6778 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perf w/Schlumberger shape charges 2/ft 5560-90 spotted 500 gal ACA on perforations broke formation down w/3000# injected acid @ 1500#. Free with 50,000 gal crude and 50,000# 20-40 sd and 35 rubber balls. IP 2300# Min 2300# Average 2500# Max 2700# Ave IR 42.3 BPM. Standing pressure 1500#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Eastern Petroleum Company
Address Val R. Reese & Assoc., Inc.
120 S. Commercial
Farmington, New Mexico

By Original signed by T. A. Dugan
Title Consulting Engineer